ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	6	Thanisandra
Street ID	**Street Name**	**Significant Landmark**
W0542, W0831, W0815, W0813, W0534, W0532, W0809, W	1st Main Rd, Panathur Colony Rd, NA, 2nd Crs, 1st Crs	Thanisandra gramatana and Surrounding areas
Segment No.	**Total Length (m)**	
6/S-W0542/S115310	457.57	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	217.46	77.633091	13.056972	77.634946	13.056800	W0811	W0538
2	37.86	77.633549	13.057016	77.633557	13.056674	W0534	W0815
3	34.10	77.633622	13.057430	77.633619	13.057122	W0534	WO532
4	95.49	77.634935	13.056386	77.635815	13.056344	W0534	DEAD END
5	72.66	77.635005	13.056754	77.635493	13.056501	W0534	DEAD END

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvement to Roads and Drains at Thanisandra gramatana and Surrounding areas in ward no 06 Byatarayanapura Sub-Division Yelahanka zone	5000000	2016
Year	**Type of Work**	**Other Work Type**
2016 - 2017	Asphalting	
Tender	**Work Details**	**Job No. / Work Code**
Not a Tender	Improvement to Roads and Drains at Thanisandra gramatana and Surrounding areas in ward no 06 Byatarayanapura Sub-Division Yelahanka zone	006-17-000007
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/146/2016-17	09/11/2016	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
28/02/2017	27/02/2018	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)

Zone: YELAHANKA **Ward No:** 6 **Ward Name:** Thanisandra **Street ID:** W0542, W0831, W0815, W0813, W0534, W

ಸಹಾಯಕ ಅಭಿಯಂತರರು
ಬಿ.ಬಿ.ಎಂ.ಪಿ. ಬ್ಯಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಬ್ಯಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ
ಬಿ.ಬಿ.ಎಂ.ಪಿ., ಬೆಂಗಳೂರು-24

KRIDL

0.00

Phone No.

9449863065

E-Mail ID

Field Inspection Details

Number of Trees

0

Any Other Information

Name

DARMASINGH

Date of Inspection

08/03/2017

Remarks

COMPLETED

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 6 **Ward Name:** Thanisandra **Street ID:** W0542, W0831, W0815, W0813, W0524, W

ಸಹಾಯಕ ಅಭಿಯಂತರರು
ಬಿ.ಬಿ.ಎಂ.ಪಿ. ಬ್ಯಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಬ್ಯಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ
ಬಿ.ಬಿ.ಎಂ.ಪಿ., ಬೆಂಗಳೂರು-24

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	08/03/2017	06/04/2017	COMPLETED
SE	VASU K M	08/03/2017	06/04/2017	COMPLETED
EE	MOHAN DAS HT	08/03/2017	06/04/2017	COMPLETED
AEE	SRIDHAR	08/03/2017	06/04/2017	COMPLETED
AE	DARMASINGH	08/03/2017	06/04/2017	COMPLETED
AE	DARMASINGH	07/03/2017	06/04/2017	COMPLETED

ಸಹಾಯಕ ಕಾರ್ಯನಿರ್ವಾಹಕ ಅಭಿಯಂತರರು
ವ್ಯಾಪಾರ ಪ್ರಾಧ್ಯಾಯನಪುರ ಉಪ ವಿಭಾಗ
ಬಿ.ಬಿ.ಎಂ.ಪಿ. ಬೆಂಗಳೂರು-24

Zone: YELAHANKA **Ward No:** 6 **Ward Name:** Thanisandra **Street ID:** W0542, W0831, W0815, W0813,